Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L5	914	(347/37).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/08/03 17:24
L6	2476	(347/86).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/08/03 17:24
S1	6	(("5278584") or ("4683481") or ("6416166")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/26 16:15
S2	. 1	10/830135	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/26 15:54
53	104796	(cartridge reservoir tank inktank) same (support carriage housing) and (slider silding\$2 adjust\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2006/07/26 16:18
S4	67172	("347").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/26 16:18
S5	4766	S3 and S4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/26 16:18
S6	39454	(cartridge reservoir tank inktank) same (support carriage housing) same (slider silding\$2 adjust\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52

S7	619	S4 and S6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/26 16:18
S8	20793	(cartridge reservoir tank inktank) same (install remov\$3 replac\$3 replacement) and (support carriage housing) same (slider sliding\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/26 16:52
S9	53297	(cartridge reservoir tank inktank) same (support carriage housing) same (slider sliding\$2 adjust\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:51
S10	908	S4 and S8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/26 16:53
S11	403	S9 and S10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/26 16:53
S12	42463	(cartridge reservoir tank inktank) same (support carriage housing) same (slid\$2 sliding\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:51
S13	29304	(cartridge reservoir tank inktank) same (support carriage housing) same (slid\$2 sliding\$2) and (install insert remov\$3 replac\$3 replacement)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:53
S14	67237	("347").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/29 12:52

S15	875	S14 and S13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52
S16	20809	(cartridge reservoir tank inktank) same (install remov\$3 replac\$3 replacement) and (support carriage housing) same (slider sliding\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52
S17	53317	(cartridge reservoir tank inktank) same (support carriage housing) same (slider sliding\$2 adjust\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52
S18	909	S14 and S16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52
S19	403	S17 and S18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52
S20	515	S15 not S19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:52
S21	1836	((cartridge reservoir tank inktank) and (support carriage housing) and (slid\$2 sliding\$2) and (install insert remov\$3 replac\$3 replacement)). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:53
S22	2685	((cartridge reservoir tank inktank) and (support carriage housing) and (slid\$2 sliding\$2) and (install insert receive remov\$3 replac\$3 replacement)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:53

S23	93	S14 and S22	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:54
S24	60	S23 not S19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/29 12:54
S25	1	10/830135	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/03 14:12

8/3/2006 5:30:25 PM C:\Documents and Settings\bgoldberg\My Documents\EAST\Workspaces\10830135 hardcopy servicing apparatus.wsp Page 4